

Issue/ Solution

HP LaserJet M3027 and M3035 MFP Product Series - Solutions provided by the 48.031.6 firmware roll



Security Level: Public

Date Written/Updated: 7/11/07

Document Summary

- ✓ This document lists solutions provided with the LaserJet M3027/35 MFP 48.031.6 firmware roll.

Issue Description:

Enhancements and Fixes provided with this Firmware revision

Notes

- This firmware release has a new feature to automatically adjust for Daylight Saving Time. After installation of the firmware, the MFP may have a control panel screen prompt for time zone or date and time. These screens will remain on the MFP until action is taken by a user. While the prompts are displayed, the MFP will still print, and receive and print faxes.
- There are isolated conditions where the time zone and Daylight Saving Time adjustment appear to be configured, but are not. Correct configuration can be verified in the EWS by going to the Start and End Date page in the EWS. A device that is not configured will have a "0" in the DST Offset field, and incorrect dates for Start Date and Stop Date. Navigate to the Start and End Date page of the EWS as follows:
[Settings]/[Date and Time]/[Advanced]/[Start Date / End Date]
- As a side effect of a high-priority fix, the EWS Print functionality does not work with this release.

Enhancements

The following new functionality or features are provided by this firmware release: (Datecode: 20070614 48.031.6)

Base Product:

- The ability to control the order in which the HP Easy Select Home Screen icons are displayed and the ability to remove them for administrative purposes has been added into the devices Embedded Web Server. The control of this new feature is found under the "Home Screen Setup" selection found on the "Settings" tab of the devices Embedded Web Server.
- The black bar across the top of the devices internal pages (i.e. Fax Report, Configuration Page, etc..) has been removed to reduce toner consumption when pages are printed frequently.

- The ability to print the HP Easy Select On-line help has been added to the device. The ability to print a single topic or all related topics has been provided.
- The ability to provide four additional languages that the walk up user can choose from at the HP Easy select control panel has been provided. The user will press the new globe icon on the control panel and choose their language. The amount of time the language is presented before going back to the default language is determined by the device's Inactivity Timer. The ability to enable this feature and to define the languages that are available are provided in the device's Embedded Web Server. The control will be found under the "Home Screen Setup" selection found on the "Settings" tab
- Added Alternate Letterhead mode to MFP firmware, selectable via the control panel under Tray Behavior. This feature should only be used when the driver does not support the functionality. Selecting the feature in both the driver and MFP will produce unexpected results.
NOTE: This release may fail (49 error) when using this feature with A5, B5, and Executive paper sizes. A fix will be available in the next release.
- The folder called "Public" is currently provided as the default storage folder for stored copy jobs. This folder has been renamed to "Untitled" to match a naming convention used by previous devices and to satisfy the numerous requests from HP customers to rename the folder. IMPORTANT NOTE: When this firmware is used to update the device, the "Untitled" folder will replace the "Public" folder and if there are existing stored jobs in the "Public" folder they will be deleted and no longer available under the new "Untitled" folder.
- Automatic Daylight Saving Time adjustment added

Digital Sending:

Note: Enhancements may not be applicable to M 3027

- When "Use address book entries only" is selected in the Embedded send-to-email configuration, end users will now be prevented from adding entries to the local address book. This enables administrators to further restrict send-to-email destinations.

Fixes or improvements

The following fixes or improvements are provided by this firmware release: (Datecode: 20070614 48.031.6)

Base Product:

- You may see a 20 Insufficient Memory error when printing certain pdf files with the postscript driver.
- When a "41.3 Load Tray X" message is presented on the HP Easy Select control panel the on-line help that is presented may reference pressing the "OK" button which may not be present on the screen
- EWS General Setting tab Help is not localized to selected EWS language
- Authentication Manager Help does not list Stored Job as a valid action
- The "Hold Off Print Job" feature was added back as a device capability. This feature allows the administrator the ability to determine how long a network print job will be delayed before printing after a copy job completes. This feature is accessible from the following menu path: ADMINISTRATION> DEVICE BEHAVIOR> GENERAL COPY BEHAVIOR> HOLD OFF PRINT JOB The time values available for this feature will be presented under the "HOLD OFF TIME" menu item which will become available after turning this feature on.

- A 49.4c02 error may be seen on the HP Easy Select control panel when printing documents with certain Franklin Gothic Book True Type Fonts.
- When selecting Manual Feed for copy paper source in German, the display is not localized.
- A 49.00FF error may occur when printing certain PDF's.
- Asian Localized languages show General Device Access Failure in EWS
- When devices Embedded Web Server is viewed in the Japanese language, the Event Log Page displays garbage characters in the "Description and Personality" field
- The short cut numerical steps provided on the Printed Menu Map are not accurate
- MFP will roll to a different NTP server when configured by hostname if named server is not available
- Intermediate and Maximum control panel lock settings do not lock tray settings. With this release, the Modify button is grayed out with these CP Lock settings
- The text for the HP Easy Select control panel Copy selection for the 2 sided to 2 sided copy selection is not localized correctly in German
- When the HP Easy Select Control Panel is set to Japanese the date and time are not presented correctly
- A 49.4c01 error may be seen almost daily on the HP Easy Select control panel when using the Scheduled Fax Printing feature.
- The Time Zones names are not displaying in the dropdown of the Advanced Date and Time page in the devices Embedded Web Server
- Some duplexed documents may output incorrectly when the print job sources paper from more than one tray on the device
- The devices Embedded Web Server's Security page is not localized correctly for UTF-8 languages
- A 49.FF09 may be seen on the HP Easy Select control panel when updating the devices firmware when devices language is set to one of the following languages (Japanese, Chinese, Korean)
- Auto Settings Reset time is based on Inactivity Timeout rather than Auto Settings Reset timer
- Event log may show values above 59 seconds instead of rolling to minutes
- A 49.5001 error may be presented on the HP Easy Select control panel.
- Device Status (i.e.. "Sleep mode on") does not display in Chinese, Japanese or Korean.
- If a print job is sent to the device while a copy job is printing, the print job may not print for a long period of time after the copy job has completed. Note: The ability to control the "Hold Off Print Job" feature has been added back into the device with this release and this feature will also intentionally delay print jobs
- Configuration page indicates Control Panel Lock set to Intermediate instead of Maximum
- Possible 49.4C02 error when selecting mixed Letter/Legal for Default Originals

Analog Fax:

- Fax volume control for receiving faxes is same audible level when switching between high and low.
- No support for localized characters in the COMPANY NAME field of the FAX HEADER in the EWS (only ASCII characters 32 to 127)
- Fax Wizard only allows 40 characters to be entered into the fax company name field.
- The 'Redial Interval' value does not remain constant across the Embedded Web Server (EWS) Digital Sending Fax settings, and Menu Fax Settings.
- When receiving faxes on a device set to French language, the name of the month in the fax header may appear incorrectly.
- The fax location may appear differently on the Menu Map and front panel when the device is set to Japanese language.
- Device may display a 49.4c27 service error if the company name is entered in the front panel Fax Wizard immediately after a firmware update (RFU).
- Unable to enter Alt or Shift+Alt characters in Company Name field when Devices Language is set to Czech.
- Faxes received in ultra-fine (400 dpi) quality may fail with an error or print out distorted.
- The Fax Call Report may print twice if a received fax fails with certain errors.
- The MFP may display a 49.4c2f service error when receiving a fax.
- Front panel fax status messages are not localized to Asian languages.
- Some fax status messages are truncated on the verbose Fax Activity Log.
- Stored faxes may not print at the scheduled time if the MFP is rebooted after they are received (and stored).
- When sending a fax to several destinations and some of the numbers fail with a "no answer", some of the numbers that were successful may not show in the Fax Activity Log.
- The status message in fax email notifications may appear incorrectly when the device is set to French language.

Digital Sending:

Note: Fixes or improvements may not be applicable to M 3027

- No warning if user enters an email address and selects Yes for "Add to Local Address Book?" and address book is full
- Broken help links in some languages for Simple Address Book
- 3rd party solutions developed using Simple Document Capture (SDC) will now work correctly when the device is added to the Digital Sending Software (DSS).
- DSS "Send To Home Folder" fails if the filename is changed by the user.

- Email subject line becomes corrupted when end users modify the default subject text. This may cause the emails to be filtered as spam by email servers.
- Long email addresses are truncated when they are added to the local address book. The limit is now extended to 64 characters.
- Blank passwords not allowed for Embedded LDAP Authentication.
- Possible 49.4c02 error while using Embedded send-to-folder.
- When BCC is disabled for send-to-email, the BCC field is not grayed out.

COMPONENT	FIRMWARE VERSION
HP LJ M3027/35 mfp	48.031.6 (Datecode: 20070614 48.031.6
DC Controller:	11*
Copy Processor Board (CPB):	2.088 (0.0)
Scanner Control Board (SCB):	MCK002 3.2
Analog Fax (xs model)	2.35u
Embedded JetDirect:	V.34.13.FF
Formatter Boot Loader	Not Applicable (HP Proprietary)

* Not included in RFU, reference only

Document Attributes

Product Models: HP LaserJet M3035 MFP Base, HP LaserJet M3035MFP XS, HP LaserJet M3027MFP, HP LaserJet M3027MFP X,

Product Numbers: CB414A, CB415A, CB416A, CB417A