


FB10000 Error Messages Troubleshooting

Error ID: 200020 – Datapath – DataEngine: Etherway cards are in simulation mode.

Error Message:



Possible Causes

- Simulation mode for Etherway was activated.

Recommended actions

Simulation mode for Etherway was activated

1. Exit the application and open Windows Explorer.
2. Under `ProgramData>HP Scitex>FB10000>Version_0.xx.xx>Configs`
3. Backup the file.
4. Open `DataEngineSettings.XML`
5. Find `<IsSimulationModeEtherway>True</ IsSimulationModeEtherway>`
6. Turn `True` to `False`
7. Restart application.
8. If the error persists restore the original file and repeat procedure.
9. If the error persists, contact `callme@hp` for support and send corrupt configuration file.

