

# Presario 2000

<b>System Board</b>	<b>Spare Part</b>	<b>System</b>
System Board, GX86, 133MHz w/ Heat Sink	285732-001	2100, 2110
System Board, GX86, 150MHz w/ Heat Sink	285815-161	2120

<b>Configuration Code</b>	<b>System Board Spare Part</b>	<b>Model</b>
BL62	285732-001	2100 (US)
BL65	285732-001	2110 (LA)
BL65	285732-001	2110 (TAI)
BL65	285732-001	2110 (APD)
BL65	285732-001	2110 (EMEA)
BL66	285732-001	2110 (NETH)
BL67	285732-001	2110 (GER/FR)
BL68	285732-001	2110 (UK)
BNQ2	285815-001	2120 (US)

<b>Memory</b>	<b>Spare Part</b>	<b>System</b>
4 MB SIMM, EDO, 60ns, Tin/Lead Contacts	285733-001	All
8 MB SIMM, EDO, 60ns, Tin/Lead Contacts	285734-001	All

<b>Miscellaneous</b>	<b>Spare Part</b>	<b>System</b>
Keyboard, US English, WIN95	285737-001	All
Speaker, Left	287525-001	All
Speaker, Right w/ Enclosure, Grommets	285720-001	All
Mouse 2-Button, Black	285728-001	All
Monitor, 14", V400, POL, NA, US	285713-001	2100, 20
Monitor, 14", V400, POL, NH, LA/TAI/APD/WW	285713-161	2110
Bezel Button Board w/ Cable	285727-001	All

<b>Hard Drives</b>	<b>Spare Part</b>	<b>System</b>
2.1 GB, IDE, 5.25"	285723-001	All

<b>CD-ROM Drive</b>	<b>Spare Part</b>	<b>System</b>
CD-ROM, IDE, 8X	285724-001	All

<b>Diskette Drives</b>	<b>Spare Part</b>	<b>System</b>
1.44 MB, 3.5"	285721-001	All

# Presario 2000

<b>36.6k-bps Modem (Data/Fax, no TAM)</b>	<b>Spare Part</b>	<b>Cable Spare Part</b>	<b>System</b>
APD	285812-001	165224-001	
Taiwan	285766-001	165224-001	
US/LA/Brazil	285729-001	165224-001	2100, 20 US; 2110 LA, Brazil

<b>28.8k-bps Modem (Data/Fax, no TAM)</b>	<b>Spare Part</b>	<b>Cable Spare Part</b>	<b>System</b>
UK only	285816-001	165224-001	2100, 20
Netherlands only	285817-001	165224-001	

<b>Cables</b>	<b>Spare Part</b>	<b>System</b>
Cable Kit: Audio, CD, HD, Diskette	285735-001	All


<b>ROM Information</b>	<b>Spare Part</b>	<b>System</b>
System ROMPaq	285461-001	2100, 20

<b>Power Supply/Battery</b>	<b>Spare Part</b>	<b>System</b>
Power Supply, 30W, Auto-Detect	285730-001	All
Battery, Replaceable, Lithium 3V, CR2032	234556-001	All


# Presario 2000

## MEMORY UPGRADE CHART

SYSTEM BOARD  
Spare Part Number 285732-001  
( 16 MB)



Memory upgrade SIMMS must be installed in pairs.  
Use SIMMs with tin/lead contacts only. EDO SIMMs  
are recommended for all system boards.



8-MB 60ns - OPTION PN 236548-001

16-MB 60ns - OPTION PN 236548-002