
HP Virtual Connect Fibre Channel Switch Firmware Support Matrix

The following table lists the switches and firmware versions that are supported with HP Virtual Connect Fibre Channel interconnect modules.

Switch family	Supported versions	Notes
Brocade HP SWD B-series	FOS 5.1.0d	<ul style="list-style-type: none">• Brocade 4/12 SAN Switch for c-Class is not supported• Brocade 4/24 SAN Switch for c-Class is not supported• HP MSA SAN switches are not supported• HP StorageWorks 2/8 EL and 2/16 EL switches are not supported• Switches with 4Gb ASIC have NPIV enabled by default• Switches with 2Gb ASIC have NPIV disabled by default• For instructions on how to enable NPIV, see the Fabric OS CLI manual or the <i>HP Virtual Connect for c-Class BladeSystem User Guide</i>
McData HP SWD M-series	E/OS 9.00.00 E/OS 8.02.00	<ul style="list-style-type: none">• McDATA Intrepid 10000 Director switch is not supported
Cisco HP SWD C-series	SAN-OS 3.0(3) SAN-OS 3.0(2a) SAN-OS 3.0(1)	<ul style="list-style-type: none">• Cisco MDS 9124e Fabric Switch for c-Class is not supported• Cisco MDS 9020 Fabric Switch is not supported• Boot from SAN is not supported with an HP QLogic QMH2462 4Gb FC HBA running firmware version 4.00.70

© Copyright 2007 Hewlett-Packard Development Company, L.P.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

April 2007 (First Edition)
Part Number 451650-001