

HP EliteBook X360 1030 G3 Notebook PC - Panel Flicker During Intimal Setup After Imaging the Computer

There is 1 file attached to this document:

- **B.7z** – batch file for introducing black screen delay before shutdown after imaging in WinPE

You may need to download this attachment and then open this using Adobe Acrobat Reader to access the attachments. If you have opened it in a Web browser you may not be able to access them.

Click the paper-clip icon in the left bar to reveal the attachments. Right-click them to download.

References: SIK1141, SID1291, SIP69759